

BCM loses communication with base station

This PDF is generated from: <https://www.nerdpublic.co.za/Sat-02-Nov-2019-10838.html>

Title: BCM loses communication with base station

Generated on: 2026-05-05 09:07:29

Copyright (C) 2026 Republic GmbH. All rights reserved.

For the latest updates and more information, visit our website: <https://www.nerdpublic.co.za>

Given the critical nature of the BCM, it's essential to identify the causes of lost communication to prevent system failure and ensure the safety of vehicle occupants.

base stationMust include: communication· base stationHarley Davidson ForumsBCM SERIOUS PROBLEM - Harley Davidson ForumsOur local dealers stock the latest part number BCM's due to the failure rate, some keep 2 in stock. The BCM supplies power to every point in the ...

This occurs when a BCM is unable to communicate with one more of a vehicle's additional control modules, such as the transmission control module, powertrain control module, or airbag ...

Discover the causes of BCM failure and how it impacts your vehicle. Learn troubleshooting tips and explore reliable, cost-effective repair options at UpFix

I've resolved most of them by doing a fresh install of Windows 10 and getting everything fully updated. I only have one problem now: the integrated BCM20703 controller chip stops working ...

Used a friends more expensive scanner and got multiple short to ground codes for the BCM. Ordered a used BCM off eBay. Should be here in the next few days, will post updated when I ...

A bad Body Control Module (BCM) can have several symptoms related to electrical problems in a vehicle. This includes any of the components that the BCM controls and manages ...

When it came to me I hooked up my TECHII to it and was able to pull codes from PCM and other modules but not from the BCM, which led me to believe I was not getting communication ...

When multiple differential modules lose communication with the Body Control Module (BCM), it often indicates BCM failure or programming issues. After installing a new BCM, it must be properly flashed ...

BCM loses communication with base station

A BCM might generate codes like U0140, indicating lost communication with the BCM, which can lead to intermittent or total loss of control over body-related functions.

Our local dealers stock the latest part number BCM's due to the failure rate, some keep 2 in stock. The BCM supplies power to every point in the bike, has the security system in it and ...

Web: <https://www.nerdpublic.co.za>

